

Hunter Cap and spindle assembly type WRC (7032944)



Hunter®

TEKNISKA SPECIFIKATIONER

Typ

WRC

PRODUKTINFORMATION

Sensor is not turning controller back on after a rain event? Remove spindle assembly to check for debris or damage to the disks.

Genererad den: 09/11/2025

Bevo Nordic A/S
Pakhusgården 54
5000 Odense C
Danmark
+45 66 19 25 45
info@bevo.dk
<http://www.bevo.com>